

**Lessee: Strike LLC**  
**Contract: 502-7691636-009**

**Unit: 2017 Volvo PL4809D**

**UNIT # 310020**  
**Location: Romco Equipment,**  
**Carmine TX**



**SPECIFICATIONS**

VIN	310020
LeaseInspector ID #	310020
Year	2017
Model	Volvo PL4809D
Location City	Carmine
Location State	TX
<b>General Specifications</b>	
New Hours	2239
Old Hours	2238

**Lessee: Strike LLC**  
**Contract: 502-7691636-009**

**Unit: 2017 Volvo PL4809D**

**UNIT # 310020**  
**Location: Romco Equipment,**  
**Carmine TX**

**ADDITIONAL FEATURES OF THIS VEHICLE**  
**COMMENTS**

**Appraiser Comments:**

**Creditor Comments:**

**Public Comments:**

**Starts/Runs:** Yes

**Overall:** Fair

**Lessee: Strike LLC**  
**Contract: 502-7691636-009**

**Unit: 2017 Volvo PL4809D**

**UNIT # 310020**  
**Location: Romco Equipment,**  
**Carmine TX**


### DEFICIENCY REVIEW

<b>ITEM</b>	<b>QTY PRICE</b>
1. Cab Bottom Dented- Not Repaired	\$0.00
2. Cab Left Front Grab Iron Dented- Not Repaired	\$0.00
3. Cab Lower Front Grab Iron Bent- Repaired	\$0.00
4. Cab Front Left Bumpers Bent- Not Repaired	\$0.00
5. Right Front Step Access Panel Stuck Closed- Repaired	\$0.00
6. Clean Engine and Hydraulic Pump Bays- Done	\$0.00
7. Dealer to Advise is Service Due- No PM	\$0.00
8. Clean and Detailer- Done	\$0.00
9. Left Mirror Lens Cracked- Repaired	\$0.00
10. Front Windshield Wiper Torn- Repaired	\$0.00
<b>Total</b>	<b>\$0.00</b>

Lessee: Strike LLC  
Contract: 502-7691636-009

Unit: 2017 Volvo PL4809D


UNIT # 310020  
Location: Romco Equipment,  
Carmin TX



Lessee: Strike LLC  
Contract: 502-7691636-009

Unit: 2017 Volvo PL4809D

UNIT # 310020  
Location: Romco Equipment,  
Carmin TX



Lessee: Strike LLC  
Contract: 502-7691636-009

Unit: 2017 Volvo PL4809D

UNIT # 310020  
Location: Romco Equipment,  
Carmin TX



Lessee: Strike LLC  
Contract: 502-7691636-009

Unit: 2017 Volvo PL4809D

UNIT # 310020  
Location: Romco Equipment,  
Carmine TX

